



# CESCOM 20 - Projected Maintenance Due

Owner: **WARREN, INC.**  
 Aircraft Model: **525B - CJ3+**  
 Aircraft Serial: **525B-0501**  
 Unit: Reg No: **N702CW**  
 Airworthiness: **28-Sep-2016**  
 Print Date: **22-Nov-2019 12:14PM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
<b>AIRCRAFT</b>	<b>1178.5</b>	<b>899</b>	<b>19-Nov-2019</b>	<b>.87</b>	<b>0.66</b>	<b>65.08</b>	<b>49</b>	<b>99</b>	<b>3</b>
<b>ENG 1</b>	<b>1178.5</b>	<b>899</b>	<b>19-Nov-2019</b>	<b>.87</b>	<b>0.66</b>	<b>65.08</b>	<b>49</b>	<b>99</b>	<b>3</b>
<b>ENG 2</b>	<b>1178.5</b>	<b>899</b>	<b>19-Nov-2019</b>	<b>.87</b>	<b>0.66</b>	<b>65.08</b>	<b>49</b>	<b>99</b>	<b>3</b>
<b>AIR COND</b>	<b>655</b>		<b>19-Nov-2019</b>	<b>.77</b>	<b>0.33</b>	<b>32.53</b>		<b>99</b>	<b>3</b>

**\*\* Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

## Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-11	INSPECTION DOCUMENT 11 (INTERVAL 1A/1C)	MTH	08-Feb-2019				29-Feb-2020	3 m 7 d		
	KBHM	HRS	891.4		300		1191.4	12.9		
		LDG	637							
5-12-23	INSPECTION DOCUMENT 23 (INTERVAL 1A/2C)	MTH	08-Feb-2019				28-Feb-2021	15 m 6 d		
	KBHM	HRS	891.4		300		1191.4	12.9		
		LDG	637							

## Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
SB WI-73-1009	R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
E1		MTH								
		RECOMMENDED	HRS				(4000)4000	2821.5		
			MSC			CSI				
SB WI-73-1009	R04 ENGINE FUEL AND CONTROL - FUEL TUBE ASSEMBLIES - REPLACE									
E2		MTH								
		RECOMMENDED	HRS				(4000)4000	2821.5		
			MSC			CSI				
SB WI-75-1001	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE									
E1		MTH								
		RECOMMENDED	HRS				(4000)4000	2821.5		
			MSC			-				
SB WI-75-1001	R01 AIR - I.P. BLEED VALVE LEVER PIN - REPLACE									
E2		MTH								
		RECOMMENDED	HRS				(4000)4000	2821.5		
			MSC			-				
SB 525B-23-05	COMMUNICATIONS - AIRCELL ATG ANTENNA BONDING IMPROVEMENTS									
			MSC							
		RECOMMENDED								
SL 525B-27-03	FLIGHT CONTROLS - ELEVATOR TRIM TAB PUSHROD REPLACEMENT									
		MTH								
		RECOMMENDED	MSC							